

S E R V I C E N O T E

SUPERSEDES: NONE

6050A Electronic Load Mainframe

Serial Numbers: See below

Error at Turnon

Duplicate Service Notes:

6050A-03 Serial Numbers: 3714A05433 / US37140161

6051A-03 Serial Numbers: 3714A00711 / US37140106

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

| P/N: | Descr: | Quantity: |
|-------------|----------------------------------|-----------|
| 06050-80018 | ROM (Revision A.03.03 or higher) | 1 |

Situation:

In some units, the unit displays errors -107 (input down), -330 (failed self-test), and -240 (hardware error) at turnon.

Solution / Action:

Replace ROM, U205, with Revision A.03.03 or higher

DATE: August 1998

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|---|-------------------------------------|---|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: | LABOR 1 Hours |
| LOCATION CATEGORY: | <input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: | <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | USED PARTS: | <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AUTHOR: GS | ENTITY: 2100 | AGILENT RESPONSIBLE UNTIL: May 2000 | |
| | | ADDITIONAL INFORMATION: None | |

