S E R V I C E N O T E

SUPERSEDES: NONE

6051A Electronic Load Mainframe

Serial Numbers: See below

Error at Turnon

Duplicate Service Notes:

6050A-03 Serial Numbers: 3714A05433 / US37140161 6051A-03 Serial Numbers: 3714A00711 / US37140106 **To Be Performed By:** Agilent-Qualified Personnel

Parts Required:

P/N: Descr: Quantity:

06050-80018 ROM (Revision A.03.03 or higher) 1

Situation:

In some units, the unit displays errors -107 (input down), -330 (failed self-test), and -240 (hardware error) at turnon.

Solution / Action:

Replace ROM, U205, with Revision A.03.03 or higher

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED					
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE □ AGREEABLE TIME	STANDARDS: LABOR 1 Hours			
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE INVENTORY:	☐ RETURN ■ SCRAP ☐ SEE TEXT	USED PARTS:	☐ RETURN ■ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: May 2000			
AUTHOR: GS	ENTITY: 2100	ADDITIONAL INFORMATION: None			

© 1998 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

