

S E R V I C E N O T E

SUPERSEDES: 3245A-02  
 Dated 09 Septemeber 1991


**3245A Universal Source**

**Serial Numbers:** 2831A00000 / 2831A01289

**Incorrectly Labeled Line Voltage Switches May Cause Switch Setting Confusion**

**Situation:**

Some units may have incorrectly labeled line voltage selection switches installed. The correct settings appear silkscreened on the instrument rear panel. The incorrect settings are silkscreened on the voltage selection switches themselves.



**Figure 1. AC Line Voltage Switch Positions**

**Solution/Action:**

No action is required. However, to avoid confusion, the incorrectly silkscreened line voltages may be easily scratched off using a flat-head screwdriver.

DATE: 01 December 1991

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
CMC	0900	