

S E R V I C E N O T E

SUPERSEDES: NONE

**6032A Autoranging DC Power Supply**

Serial Numbers: See Below

**Misloaded Fuse**

**Duplicate Service Notes:**

6012B-08 Serial Numbers: US35430121 / US35430170

6032A-19 Serial Numbers: US35420201 / US35420440

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:**

P/N: 2110-0001 Descr: Fuse Quantity: 1

**Situation:**

The wrong type of fuse was loaded into some units.

**Solution / Action:**

When fuse F1 is NOT rated for 1 Amp, replace it with 2110-0001.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: GS	ENTITY: 2100	AGILENT RESPONSIBLE UNTIL: April 2000	
		ADDITIONAL INFORMATION: None	

**Serial Numbers:**

See Below

**Misloaded Fuse**

**Duplicate Service Notes:**

6012B-08 Serial Numbers: US35430121 / US35430170

6032A-19 Serial Numbers: US35420201 / US35420440

**To Be Performed By:**

Agilent-Qualified Personnel

**Parts Required:**

P/N: 2110-0001 Descr: Fuse Quantity: 1

**Situation:**

The wrong type of fuse was loaded into some units.

**Solution / Action:**

When fuse F1 is NOT rated for 1 Amp, replace it with 2110-0001.