S E R V I C E N O T E

SUPERSEDES:6625A-08, 6626A-08, 6628A-08, 6629A-08

6625A Multiple Output DC Power Supply

Serial Numbers: See below

Replacing the GPIB or LCD Display

Duplicate Service Notes:

6625A-08A Serial Numbers: 0000A00000 / 3738A01389 6626A-08A Serial Numbers: 0000A00000 / 3737A02259 6628A-08A Serial Numbers: 0000A00000 / 3738A00683 6629A-08A Serial Numbers: 0000A00000 / 3738A00968

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Description	Part No.	Quantity
Tested GPIB	5063-4837	1
LCD Display	5063-3472	1

Continued

DATE: December 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:		
INFORMATION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:	
GS	2100		

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The LCD (P/N 5063-2304) has been replaced by an LCD without a translator chip (P/N 5063-3472) and the decoding has been moved to the GPIB board (which has also been changed). Therefore the older LCD/GPIB board is not compatible with the newer GPIB board/LCD. The older GPIB has P/N 5060-3437 while the new GPIB has P/N 5063-4837.

Solution / Action:

When inventory is depleted and the older GPIB board needs to be replaced, replace both the GPIB board and the LCD with their newer versions. LCD 5063-2304 with the translator chip is still available.