# INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

6671A-03A

## <u>SERVICE NOTE</u>

Supersedes: 6671A-03

## 6671A DC Power Supply

Serial Numbers: 0000A00000 / 3624A00583

Downprogramming FET's Q901 no longer have an isolated package

To Be Performed By: Agilent-Qualified Personnel or Customer

**Parts Required:** 

**P/N Description Qty.** 5063-3418 Kit, Downprogrammer- Svc, 5063-3418

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

### **INFORMATION ONLY**

AUTHOR: DF/RJM PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



June 3, 2002

Page 2 of 2 6671A-03A

#### **Situation:**

The original part Agilent p/n 1855-0834 has been discontinued by the manufacturer and the replacement part does not have an isolated package. Therefore, it cannot be mounted directly to te heat sink.

#### **Solution/Action:**

If the original part fails it may be replaced by the service kit p/n 5063-3418. The kit consists of a new FET, p/n 1855-0874, and an insulator, p/n 0340-1507.