# S E R V I C E N O T E

SUPERSEDES: NONE

## 8164A Lightwave Measurement System

**Serial Numbers:** Potential units from DE38700101 to DE38701400.

All 8164A Mainframes w/ firmware revision 2.02 and lower.

manufactured before May, 31,2000

## 8164A FW revision 2.02 and lower

To Be Performed By: Customers

**Parts Required:** Two floppy discs with newest firmware revision

installed to update the mainframe firmware.

#### **Situation:**

Occasionally, when an 8153x Power Meter ranges from the lowest range to the highest range the system locks up or the following assertion occurs:

"Assertion failed: buf->bufhdr.bufowner = owned by ISR

file message.cpp, line 179

Task: interrupt"

### **Solution / Action:**

Installation of firmware revision v2.03 (or higher) to the 8164A mainframe. The firmware and the process how to install it is available from the internet on the Technical Support Main page on URL:

http://www.tm.agilent.com/tmo/TechSupp/English/index.html

DATE: July 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS:  LABOR 0.5 Hours
LOCATION CATEGORY:	<ul><li>■ CUSTOMER INSTALLABLE</li><li>□ ON-SITE</li><li>□ SERVICE CENTER</li></ul>	SERVICE ☐ RETURN USED ☐ RETURN PARTS: ☐ SCRAP ☐ SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: May 2003
AUTHOR: VE	ENTITY: OCMD	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

