16550A-01

S	Е	R	V	Ι	С	Е	Ν	0	Т	Е	
]	SUPERSEDES: None										
1	Serial Numbers: US00000/US99999										
	 Serial Numbers: US00000/US99999 Duplicate Service Notes: 16550A-01 16554A-01 16555A-03 16556A-01 Cables can be purchased by Agilent Personnel or customers. Stuation: The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above. Solution / Action: The two cables are being replaced by the part number 16710-61603, Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are: 01660-60007: Consists of four 16710-61603 cables. 01661-60001: Consists of three 16710-61603 cables. 01662-60001: Consists of two 16710-61603 cables. 01662-60001: Consists of nor 16710-61603 cables. 01662-60001: Consists of nor 16710-61603 cables. 										
							DATE: Nove	mber 20	01		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:	
	INFORMAT	ION ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AR	0800	
© 2001 AGILENT TEC PRINTED IN U.S.A.	HNOLOGIES	Agilent Technologies