1662AS-03

S	Е	R	V	Ι	С	Е	Ν	0	Т	Е
	SUPERSEDES: None									
	Serial Numbers: US00000/US99999									
	Duplicate	Service]	1 1	660A-03 661A-03 662A-03 663A-03	166 166	0AS-03 1AS-03 2AS-03 3AS-03				
	Cables can be purchased by Agilent Personnel or customers.									
	Situation:									
	The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.									
	Solution / Action:									
	The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:									
	01660-60007: Consists of four 16710-61603 cables. 01661-60001: Consists of three 16710-61603 cables. 01662-60001: Consists of two 16710-61603 cables. 16710-61603: Consists of one 16710-61603 cable.									
							DATE: Nov	ember 20	001	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:	
	INFORMAT	ION ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AR	0800	
© 2001 AGILENT TEC	HNOLOGIES	
PRINTED IN U.S.A.		Agilent Technologies