1670A-02

S	Е	R	V	I	С	Е	Ν	0	Т	Е		
	SUPERSEDES: None											
	Serial Numbers: US00000/US99999											
	Duplicate Service Notes:1670A-021671A-031672A-02Cables can be purchased by Agilent Personnel or customers.											
	 Situation: The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above. Solution / Action: The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are: 01660-60007: Consists of four 16710-61603 cables. 01661-60001: Consists of three 16710-61603 cables. 01662-60001: Consists of not 16710-61603 cables. 16710-61603: Consists of one 16710-61603 cables. 											
	DATE: November 2001											

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	-							
INFORMATION ONLY								
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:						
AR	0800							
© 2001 AGILENT TEC	HNOLOGIES	. 1 .						
PRINTED IN U.S.A.		Agilent Technologies						