1671E-01

S	Е	R	V		С	Е	Ν	0	Т	Е		
	SUPERSEDES: None											
	Serial Numbers: US00000/US99999											
	Duplicate 1670E-01	Service	Notes:	16	71E-01							
	1672E-01 Cables can be purchased by Agilent Personnel or customers.											
	Situation:											
	The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.											
	Solution / Action:											
	The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:											
	01660-60007: Consists of four 16710-61603 cables. 01661-60001: Consists of three 16710-61603 cables. 01662-60001: Consists of two 16710-61603 cables. 16710-61603: Consists of one 16710-61603 cable.											
	DATE: November 2001											

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:				
	INFORMAT	ION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:			
AR	0800				
© 2001 AGILENT TEC	HNOLOGIES				
PRINTED IN U.S.A.		Agilent Technologies			