1672A-02

S	Е	R	V	I	С	Е	Ν	0	Т	Е	
	SUPERSEDES: None										
	Serial Numbers: US00000/US99999										
	Duplicate Service Notes:1670A-021671A-031672A-02Cables can be purchased by Agilent Personnel or customers.										
	<ul> <li>Situation:</li> <li>The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.</li> <li>Solution / Action:</li> <li>The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:</li> <li>01660-60007: Consists of four 16710-61603 cables.</li> <li>01661-60001: Consists of three 16710-61603 cables.</li> <li>01662-60001: Consists of two 16710-61603 cables.</li> <li>16710-61603: Consists of one 16710-61603 cables.</li> </ul>										
	DATE: November 2001										

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:	
	INFORMATI	ON ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AR	0800	
© 2001 AGILENT TEC PRINTED IN U.S.A.	HNOLOGIES	Agilent Technologies