

S E R V I C E N O T E

SUPERSEDES: NONE

**E8603A Calibration Executive Software**

**Serial Numbers:** NA

**CES release 1.53**

**To Be Performed By:** Agilent-Qualified Personnel only.

**Situation:**

The released build 1.52.10 of the CS contains several bugs. All 1.52.8, and 1.52.10 installations must be updated to release 1.53.5. The upgrade is a software-only upgrade; the firmware has not changed from 1.52.10.

<b>Software:</b>	<b>Firmware:</b>				
CES	VM30	CON2*	PCOM	PWM	SIU
1.53.5	2.09.9	1.09.0	1.02.1	1.02.2	1.06.3

\*CON2 hasn't changed from 1.52.8.

**Solution / Action:**

This service note allows the unconditional installation of the software to customers who bought 1.5, and have 1.52.x installed, at no charge. For customers having older (1.51.x) versions, please refer to the relevant service notes. 1.4.x and older require purchase of an upgrade package.

DATE: July 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AUTHOR: PdH	ENTITY: 4222	AGILENT RESPONSIBLE UNTIL:	
		ADDITIONAL INFORMATION:	

