

S E R V I C E N O T E

SUPERSEDES: None

70810B Lightwave Section

Serial Numbers: 0000A00000 / 3138A00653

Exceptions: 3103A00115, 3103A00117 / 3103A00122

Installation of new firmware Date Code 910927

To Be Performed By: Agilent-Qualified Personnel

Situation:

A firmware defect was uncovered in the initial release of the 70810B firmware. The defect was a reversal of two signs in the 70810B's capability string.

The 70810-60032 ROM/RAM Board is being replaced with the 70810-60034 ROM/RAM Board. The ROM/RAM Board is part of a Firmware Upgrade Kit (P/N 70810-60035) which also includes an Installation Note.

DATE: 23 March 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: BSC	ENTITY: 5300	AGILENT RESPONSIBLE UNTIL: 23 March 1993	
		ADDITIONAL INFORMATION:	

