

S E R V I C E N O T E

SUPERSEDES: None

8711A RF Network Analyzer**Serial Numbers:** 0000A00000 / 9999A99999**Incorrect part source listed in service manual****Situation:**

The 8711A manual lists a 75 ohm 20dB attenuator as required equipment. At the time of writing the manual, no part number was available so we listed the name and phone number of a company that could provide the part. Unfortunately, the company has moved and the phone number listed now belongs to a private residence. PLEASE DO NOT CALL THIS NUMBER!!! There is now a part number set up for this attenuator: P/N 0955-0670.

Change your 8711A Service Manual (08711-90003 edition 2) as follows:

Page 1-3: Delete Huber-Suhner Co. reference and replace with P/N 0955-0670
Delete footnote 3 reference

Page 1-4: Delete footnote 3

Page 2-13: Delete Series 6800 reference in 75 ohm equipment list and replace with
p/n 0955-0670
Delete footnote 2

NOTE:

Edition 1 manuals had the same problem on page 2-10,
although no phone number was listed.

DATE: 05 January 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: JV	ENTITY: 4500	ADDITIONAL INFORMATION:
-------------------	---------------------	-------------------------