

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**E5071B-09A**

**S E R V I C E N O T E**

Supersedes:  
E5071B-09

E5071B RF Network Analyzer, 300 kHz to 8.5 GHz

Serial Numbers: MY42301392 / MY42301541

**One or two units might have been shipped with wrong keypad rubber**

**To Be Performed By: Agilent-Qualified Personnel**

**Parts Required:**

P/N	Description	Qty.
E5070-25101	Keypad Rubber	1

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.3 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Sep 2006	
AUTHOR: KW		PRODUCT LINE: WN	
ADDITIONAL INFORMATION:			


© AGILENT TECHNOLOGIES, INC. 2004  
PRINTED IN U.S.A.



September 21, 2004

**Situation:**

Analyzers specified above might have a wrong keypad rubber.



**Solution/Action:**

Replace the wrong keypad rubber with a correct one.