
11722A-01



ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:	
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
LHL	1000	

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Solution/Action:

Replace original Main Deck Plate (MP1) and associated hardware with part numbers noted above. Refer to Figure 1 for correct mechanical and electrical connections. Recalibration and generation of Calibration Factors for the Sensor Module is recommended after coaxial switch replacement.

1. Disassembling




Figure 1