

S E R V I C E N O T E

SUPERSEDES: None

8662A Synthesized Signal Generator

Serial Numbers: 2712A0000 / 3117A04065

Modification Kit to correct Error 03/04 conditions.

Parts Required:

- 08662-60520 Error 03/04 Retrofit Kit (New)
- 08662-69015 Error 03/04 Retrofit Kit (Exchange)

Situation:

The Low Frequency Loops (A3 section) of the 8662A has been modified to eliminate the possibility of intermittent conditions where the VCO will quit oscillating, resulting in Error 03, Error 04 or both.

NOTE:

Although 8662As with serial prefixes below 2712A are not covered by this Service Note, installing this kit in older 8662As (at customer expense) will also eliminate similar conditions.

Solution/Action:

To modify 8662As with this problem, a Modification Kit is available (see Parts Required).

DATE: 07 April 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 2.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: DT	ENTITY: 1000	AGILENT RESPONSIBLE UNTIL: 01 May 1995	
		ADDITIONAL INFORMATION:;	

