

S E R V I C E N O T E

SUPERSEDES: NONE

8663A Synthesized Signal Generator

Serial Numbers: 3842A02691 / 3909A02751

Procedure to resolve 230V misprinted fuse rating on fuse plate.

Duplicate Service Notes: 8662A-20 S/N 3842A04698 / 3909A04738

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

| Agilent P/N | Description | Quantity |
|-------------|----------------------------|----------|
| N/A | Sticker with "2.5A" rating | 1 |

Situation:

There is a misprinted fuse rating value on the fuse plate in rear of the 8662A/8663A for 230V. The printed value should be 2.5A instead of 1.5A. If the customer would used 1.5A fuse, the worst case would be that the fuse would blow without any further damaged to the unit.

Solution / Action:

The correct sticker label with "2.5A" will be put on the fuse plate to cover the "1.5A" label. Customer can make the label by typing "2.5A" on a sticker label and place over the "1.5A" on fuse plate of the 8662A/8663A or contact Son Nguyen at 707-577-5977 for a pre-made Sticker label.

DATE: March 2000

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|--|---------------------------------------|--|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: | LABOR 15 min Hours |
| LOCATION CATEGORY: | <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | USED PARTS: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AUTHOR: SN | ENTITY: 5331 | AGILENT RESPONSIBLE UNTIL: April 2003 | |
| | | ADDITIONAL INFORMATION: | |