

8664A-11

S E R V I C E N O T E

Supersedes:
None

8664A Synthesized Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

Situation:

A15 Attenuator/RPP assembly part numbers are incorrect as documented in the hardcopy and electronic versions of the Assembly Level Repair Service Diagnostics Manual P/N: 08645-90145

Parts Required:

P/N	Description
A15 08664-61003	ATTENUATOR/RPP ASSEMBLY (NEW) FITS ANY CONFIGURATION EXCEPT OPT 008
A15 08664-61004	ATTENUATOR/RPP ASSEMBLY (NEW) FITS ANY CONFIGURATION WITH OPT 008

Note: Exchange parts are likely no longer available for these assemblies.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <div style="text-align: center; font-weight: bold; font-size: 1.2em; margin-top: 10px;"> INFORMATION ONLY </div>
AUTHOR: AKS PRODUCT LINE: PL15 / 5320
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



Situation:

The last published printing of the Assembly Level Repair Service Diagnostics Manual (ALRSDM) P/N: 08645-90145 (Jan 98) documented the wrong replacement parts in the Table 4-4 Replaceable Parts section for the 8664A.

The 8664A model of the PSG Classic family uses different A15 Attenuator/RPP assemblies than other models of the same family. The incorrect P/N's currently documented in the ALRSDM for the 8664A are inadvertent duplication of the same P/N's that the 8665A model uses.

The correct P/N's for use in the 8664A are the ones listed above. Due to the age of the documentation there is no process for providing filed updates to the ALRSDM.

Solution/Action:

This Service Note should be used as an erratum to update existing ALRSDM hard or printed electronic copies.

During a repair, if the faulty assembly is identified to be the A15 assembly then one of the appropriately optioned P/N's should be ordered as the replacement assembly. Exchange material may no longer be available thus only the new P/Ns above are obtainable.