|   |         |            |          | E25                        | 05A         | -01     |
|---|---------|------------|----------|----------------------------|-------------|---------|
| SERVI   | С       | Е          | Ν        | 0                          | т           | Е       |
| E2505A Frequency Agile Signa  | l Simı  | _          |          | DES: No<br><b>(Iodel 2</b> | -           |         |
| Serial Numbers: 0000A00000 / 9999A9   | 9999    |            |          |                            |             |         |
| Incorrect Reference Designators<br>Test 3XX of the 86793A Agile Mic   | -       |            |          | -                          | nostics     | ;       |
| Duplicate Service Notes: 86793A-01  |         |            |          |                            |             |         |
| Parts Required: None  |         |            |          |                            |             |         |
| Situation:  |         |            |          |                            |             |         |
| When running diagnostics tests on the 867<br>Revision 1.43 and below will return on Te<br>designators for checking. | •       |            |          |                            | r, Firmwa   | are     |
| Solution/Action:  |         |            |          |                            |             |         |
| Use the attached table to cross reference to vision of Firmware is released.  | the cor | rect refei | ence des | ignator ui                 | ntil the ne | ext re- |
|   |         |            |          |                            |             |         |
|   |         |            |          |                            |             |         |
|   |         |            |          |                            |             |         |
|   |         |            |          |                            | 6           | ,• • •  |
|   |         |            |          | April 199                  |             | ntinued |

## ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION:<br>INFORMATION ONLY |                 |                         |  |  |  |
|--|-----------------|-------------------------|--|--|--|
| AUTHOR:<br>DGS                                   | ENTITY:<br>0400 | ADDITIONAL INFORMATION: |  |  |  |
|  |                 |                         |  |  |  |

1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



| What Firmware reports:    | What should be checked:  |  |  |
|---------------------------|--------------------------|--|--|
| -60101 Assembly           | A6A1                     |  |  |
| -60102 Assembly           | A6A2                     |  |  |
| A5A3                      | A5U1                     |  |  |
| A5A1                      | A5U2                     |  |  |
| A5A2                      | A5U3                     |  |  |
| A5A4                      | A5U6                     |  |  |
| A5FL1                     | A5FL3                    |  |  |
| A5FL3                     | A5FL5                    |  |  |
| A5FL4                     | A5FL6                    |  |  |
| A5FL5                     | A5FL8                    |  |  |
| A5FL6                     | A5FL9                    |  |  |
| A5FL7                     | A5FL10                   |  |  |
| A5FL8                     | A5FL11                   |  |  |
| A3U1                      | A3U3                     |  |  |
| A3U3                      | A3U2                     |  |  |
| Check RFin(XXXHz -10 dBm) | Check RFin (XXXHz 0 dBm) |  |  |