E2507B-01

E2507B MCSS model 60

Serial Numbers:

US00000000 / US95200177

Y2K update information. Product requires software patches on Windows 3.1 software and possibly on the computer BIOS. The patches are available on the following URLs:

Windows 3.1

http://www.microsoft.com/technet/topics/year2k/product/product.htm

BTOS:

http://www.hp.com/desktop/support/year2000/y2k-solution.html

To Be Performed By: HP-Qualified Personnel or Customer

Situation:

MCSS system include PC with Windows 3.1. The MCSS software is Y2K compliant; however, the BIOS may not be compliant and Windows 3.1 is compliant with minor issues. Problems may be encountered when utilizing the MCSS software in conjunction with Windows or when utilizing the PC as a personal computer rather than an MCSS controller.

Solution / Action:

Download the patches that are available at the websites listed above and follow the manufacturers instructions for installation.

Date: March 1999

			*
MODIFI	CATION RECOMMENDED		*
			*
			*
STANDARDS:	LABOR HOURS 0.5		*
ACTION CATEGORY:	ON SPECIFIED FAILURE	IMMEDIATELY	*
	AGREEABLE TIME XX		*
LOCATION CATEGORY:	CUSTOMER INSTALLABLE XX	ON-SITE	*
	HP LOCATION		*
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		*
SERVICE INVENTORY:	RETURN SCRAP	SEE TEXT xx	*
USED PARTS:	RETURN SCRAP	SEE TEXT xx	*
HP RESPONSIBLE UNTI	L:_Product support life		*
AUTHOR/ENTITY:	LF_ /5340		*
ADDITIONAL INFO:			*
* * * * * * * * * * * * * * * * * * * *	*******	******	*