

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**E8241A-07A**

**S E R V I C E N O T E**

---

Supersedes:

E8241A-07

E8241A

Serial Numbers: [0000A00000 / 9999Z99999]

**Lowband output assembly failure and causes “unleveled” condition.**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
E8251-69046	Lowband output assembly	1
Or, if 69046 is not available		
E8251-60046	Lowband output assembly	1

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: HLU      PRODUCT LINE: 15

ADDITIONAL INFORMATION:

Agilent responsible for repair parts only until 1AUG2006

© AGILENT TECHNOLOGIES, INC. 2005  
PRINTED IN U.S.A.



August 15, 2005

**Situation:**

**Repeat failures of lowband assembly E8251-60046 cause “unleveled” condition.**

**Solution/Action:**

**Agilent is responsible for E8251-69046 or E8251-60046 part; no labor or calibration is included, until 1AUG2006.**