

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E8244A-02

S E R V I C E N O T E

Supersedes:
None

E8244A PSG-A Series Performance Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

For reliability improvement and enhancements, it is recommended to upgrade firmware for E8244A to C.01.24 or greater.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
		USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 11, 2005
AUTHOR: Son Nguyen PRODUCT LINE: 15		
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.



September 12, 2003

Situation:

Firmware C.01.24 improves the reliability for low band output module.

Solution/Action:

The firmware upgrade process can be obtained at the URL:

http://we.home.agilent.com/cgi-bin/bvpub/agilent/editorial/cp_MiscEditorial.jsp?OID=536913874&NAV_ID=-536891161.536881801.03&LANGUAGE_CODE=eng&COUNTRY_CODE=ZZ