

MODIFICATION AVAILABLE – PERFORMANCE ENHANCEMENT
CHARGEABLE TO CUSTOMER .

E8244A-04

S E R V I C E N O T E

Supersedes:
None

E8244A PSG Analog Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

Adding an Hi Power option 1EA To E8244A

To Be Performed By: Agilent-Qualified Personnel
Only Agilent installable, not customer installable.

Parts Required:

P/N	Description	Qty.
N/A		

Situation:

To provide the ability to add a Hi Power (option 1EA) to E8244A at Agilent service centers.

Solution/Action:

Installation of this option requires using information in the Assembly Replacement and Replaceable Parts sections of the Service Guide for PSG Signal Sources Generator (E8251-90259) and having access to the PC LAN and a valid IP address. There are 3 parts to installing the Hi Power option 1EA.

- I. Contact customer support to update the instrument's files
- II. Adjust and performance test the instrument.
- III. Pricing

Updating files:

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	X PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER	AVAILABLE UNTIL: 2 years before End of support
AUTHOR: SN PRODUCT LINE: 15		
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



January 28, 2004

Updating the files requires the instrument be connected to a PC LAN that can be accessed by the support engineer. The PC LAN can be inside or outside the Agilent's firewall.

1. Notify the support engineer by email at PGU, SOURCES of the model number xxx, serial number xxx, with options xxx installed, will be connected to the PC LAN at IP address xxxxxxxx, and needs option 1EA installed.
the date and time the instrument will be available on the PC LAN for updating
The support engineer will then reply letting you know if they are available on that date to do the updating.
2. To be able to access the instrument, the IP address, Subnet Mask, and Default Gateway must be loaded in to the instrument. After the instrument is connected to the PC LAN and turned on, the support engineer will be able to access it from his desk and update the files.
3. On the agreed upon date, connect the instrument to the PC LAN, turn it on and leave it for 24 hours or until notified the file update is complete.

Adjustments and Performance Testing:

4. N/A

Pricing:

The price for upgrading to 1EA may vary from service center to service center. But the minimum price the customer is to be charged for adding option 1EA (parts and labor) must be equal to the price the customer would have paid if the option were purchased with the instrument. The service center may choose to charge more than the price paid for the option at the time the instrument was purchased.

Example: Opal price for option 1EA at time of purchase is \$5200.00 Upgrade cost \geq \$5200.00

Estimated Time:

Hardware installation: N/A

Files updated: 1 Hr