

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E8254A-08A

S E R V I C E N O T E

Supersedes:
E8254A-08

E8254A

Serial Numbers: [0000A00000 / 9999Z99999]

Lowband output assembly failure and causes “unleveled” condition.

Parts Required:

| P/N | Description | Qty. |
|-------------------------------|-------------------------|-------------|
| E8251-69046 | Lowband output assembly | 1 |
| Or, if 69046 is not available | | |
| E8251-60046 | Lowband output assembly | 1 |

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: HLU PRODUCT LINE: 15

ADDITIONAL INFORMATION:
Agilent responsible for repair parts only until 1AUG2006

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



August 15, 2005

Situation:

Repeat failures of lowband assembly E8251-60046 cause “unleveled” condition.

Solution/Action:

Agilent is responsible for E8251-69046 or E8251-60046 part; no labor or calibration is included, until 1AUG2006.