

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E8267C-11

S E R V I C E N O T E

Supersedes:
None

E8267C Vector Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

Unexpected loss or change to WRM files in volatile memory in instruments with option 002 or 602.

Parts Required:

P/N	Description	Qty.
none		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DMc PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



February 15, 2006

Situation:

Unexpected loss or change to WFM files in volatile memory in instruments with option 002 or 602.

Solution/Action:

Upgrade firmware to C.03.85.