Installation Note

Agilent Technologies 8560 E-Series Firmware Upgrade Kit 08560-60090

Part Number 08560-90164 Printed in USA May 2001 Supersedes: December 1999 Notice. The information contained in this document is subject to change without notice.

Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Agilent 8560 E-Series Firmware Upgrade Kit

Instruments Affected: 8560E spectrum analyzers

8561E spectrum analyzers 8562E spectrum analyzers 8563E spectrum analyzers 8564E spectrum analyzers 8565E spectrum analyzers

Serial Numbers: Serial prefix 3850A and below

To Be Performed By: Customer or Agilent-qualified personnel

What You'll Find in This Installation Note

This installation note describes how to upgrade the firmware in an 8560 E-Series spectrum analyzer.

Note

Spectrum analyzers with firmware revision 960401 and later are not compatible with Agilent 85620A Mass Memory Modules with internal firmware revisions A and B (date codes 890214 and 890524).

For spectrum analyzers containing firmware revision 94021 or later, simply replace the firmware chips with those contained in this kit. **Do not use the A2/firmware upgrade software.**

For spectrum analyzers containing firmware revision 930809 or earlier, see the following:

Note

Either of two different kits must be installed, depending on the CPU clock speed of the spectrum analyzer (8 MHz or 16 MHz). If the firmware revision is 920528, the CPU clock is 8 MHz. For any other firmware revisions, up to and including 930809, you can determine the CPU clock speed by pressing (PRESET), (SPAN), 1 kHz. If the annotated sweep time is 477 ms, the CPU clock is 16 MHz. If the annotated sweep time is 740 ms, the CPU clock is 8 MHz.

Note

Do not use the software included in this kit with instruments whose firmware revision is 940210 or later.

- If the CPU clock is 8 MHz, the A2 Controller Board Kit (08563-60058) must be ordered and installed. The A2 Controller Board Kit contains the A2/firmware upgrade software (this software should only be used with an instrument whose prefix is less than 3310A), and has the latest firmware ROMS installed on the A2 controller assembly.
- If the CPU clock is 16 MHz, the EEROM upgrade may be needed. As shipped from the factory, 8560E, 8561E, and 8563E instruments with serial prefixes 3310A through 3410A will require this upgrade. Kit (5063-0669) must be ordered and installed.
- Serial Prefixes ≤3329A (for 8561E only) require a new A14 frequency control board to be ordered and installed. This is in addition to the above EEROM or controller board change requirements.

After a new A2 controller is installed or the EEROM is changed, the spectrum analyzer serial number and identification (ID) string must be downloaded into the EEROM. Option 008 will be added to the ID string if necessary. The spectrum analyzer frequency response will also be readjusted since the new correction points are in different memory locations in the new larger EEROM.

Note

The new A2 controller phase-locks its CPU clock to the 10 MHz reference from the A15 RF assembly. With older A15 RF assemblies, if the spectrum analyzer is placed into external reference mode without an external reference supplied, no 10 MHz reference will be supplied to the A2 Controller. The display will appear distorted if no 10 MHz reference is supplied to A2. This is normal.

Safety Considerations

Warning

Before you disassemble the instrument, turn the power switch OFF and unplug the spectrum analyzer. Failure to unplug the spectrum analyzer can result in personal injury.

Caution

Electrostatic discharge (ESD) can damage or destroy electronic components. All work on electronic assemblies should be performed at a static-safe work station. Refer to the appropriate spectrum analyzer calibration guide for information about a static-safe work station and ordering static-safe accessories.

Items Shipped with Installation Kit

Table 1-1 lists the parts shipped with the 8560 E-Series Firmware Upgrade Kit, part number 08560-60090.

Table 1-1. Firmware Upgrade Kit Parts List

Quantity	Description	Part Number
1	EPROM, programmed U306	08564-80057
1	EPROM, programmed U307	08564-80058
1	EPROM, programmed U308	08564-80059
1	EPROM, programmed U309	08564-80060
1	EPROM, programmed U310	08564-80011
1	EPROM, programmed U311	08564-80012
1	Installation note	08560-90164
1	A2/firmware upgrade software	5010-7725
1	8560 Series firmware note	08560-90163

Required Tools

Table 1-2 lists the tools required to install the new firmware assembly.

Table 1-2. Required Tools

Description	Part Number
4-mm hex (Allen) wrench	8710-1164
T-10 TORX screwdriver	8710-1623
#1 Pozidrive screwdriver	8710-0899

Required Equipment

Table 1-3 lists the equipment required to run the A2 firmware upgrade software and perform the frequency response adjustment. An Agilent 85629B test and adjustment module (TAM) is recommended for performing the frequency response adjustment on the 8560E, 8561E, and 8563E.

Table 1-3. Required Test Equipment

Test Equipment	Recommended Model Number
Synthesized sweeper (8560E, 8561E, or 8563E)	8340A/B
Measuring receiver	8902A
Power splitter (8563E)	11667B
Power splitter (8560E or 8561E)	11667A
Power sensor	8482A
Power sensor (8563E)	8485A
Power sensor (8560E or 8561E)	8481A
Computer (with HP Basic 3.0 or later)	HP 9000, Model 216
(8560E, 8561E, or 8563E)	236 or 310
Adapters	
Type-N (m) to APC 3.5 (m)	1250-1743
Type-N (f) to APC 3.5 (m)	1250-1750
APC 3.5 (f) to APC 3.5 (f)	5061-5311
Cables	
BNC, 122-cm (48 in)	10503 A
APC 3.5, 91-cm (36 in)	8120-4921
GPIB, 2-m	10833B

Installation Procedure

This installation procedure includes several tasks. Not all of the tasks are required for different model numbers and serial numbers. Do the tasks in the following order, but skip the ones that are not appropriate for your particular spectrum analyzer.

Record the EEROM Data (instruments with firmware <930809 only)

This procedure is only required for the 8560E, 8561E and 8563E. See "What You'll Find in This Installation Note" for information about the appropriate serial numbers.

- 1. Remove the spectrum analyzer cover assembly. This is described in procedure 1 of Chapter 3 in this note.
- 2. Move the WR PROT/WR ENA jumper on the A2 controller assembly to the WR ENA position.
- 3. Connect a power cord to the spectrum analyzer and set the LINE switch ON. Wait for the power-on adjustments to complete.
- 4. Press (CAL), MORE 1 OF 2, SERVICE CAL DATA.
- 5 · If the spectrum analyzer is not an 8560E with Option 002, press 3RD IF AMP, EXT MXR REF CAL. Record the displayed EXT MXR REF CAL below.

EXT MXR REF CAL _____ Vdc

- 6. On the spectrum analyzer, press (PRESET), and set the controls as follows:
- 7. Press (CAL), MORE 1 OF 2, SERVICE CAL DATA, LO LEVELS, LO GATE LEVEL. Record the LO GATE DAC value in Table 2-1.
- 8. Press INT LO LEVEL. The message DRIVE FOR BAND# 0 should be displayed. Record the LO DRIVE DAC value for Band 0 in Table 2-1.
- 9. Skip to step 14 if the spectrum analyzer is an 8560E.
- 10. Press (1). The message DRIVE FOR BAND# 1 should be displayed. Record the LO DRIVE DAC value for Band 1 in Table 2-1.
- 11. Skip to step 14 if the spectrum analyzer is an 8561E.
- 12. Press (1). The message DRIVE FOR BAND# 2 should be displayed. Record the LO DRIVE DAC value for Band 2 in Table 2-1.

- 13. Press ①. The message DRIVE FOR BAND# 3 should be displayed. Record the LO DRIVE DAC value for Band 3 in Table 2-1.
- 14. Press EXT LO LEVEL. Record the LO DRIVE DAC value for External mixing in Table 2-1.

Table 2-1. LO Levels DAC Values

Local Oscillator DAC	DAC Value
LO GATE DAC	
LO DRIVE DAC, Band 0	
LO DRIVE DAC, Band 1	*
LO DRIVE DAC, Band 2	
LO DRIVE DAC, Band 3	†
LO DRIVE DAC, External	
* Applies only to 8561E a	nd 8563E.
† Applies only to 8563E.	

15. If the spectrum analyzer is an 8561E, press BAND 1 MXR BIAS. Record the INT MXR BIAS DAC value below.

INT MXR BIAS DAC _____

- 16. Press PREV MENU.
- 17. If spectrum analyzer is an 8560E, skip to step 27.
- 18. On the spectrum analyzer, press (PRESET), and set the controls as follows:

Center frequency	 4.0 GHz
Span	 0 Hz

- 19. Press CAL, MORE 1 OF 2, SERVICE CAL DATA, PRESEL ADJ, PRESEL OFFSET. Record the PRESEL OFFSET DAC value for Band 1 in Table 2-2.
- 20. If spectrum analyzer is an 8561E, skip to step 23.
- 21. Press (1). Record the PRESEL OFFSET DAC value for Band 2 in Table 2-2.
- 22. Press (1). Record the PRESEL OFFSET DAC value for Band 3 in Table 2-2.
- 23. Press PRESEL SLOPE. If necessary, press \$\empty\$ until the message SLOPE FOR BAND # 1 is displayed. Record the PRESEL SLOPE DAC value for Band 1 in Table 2-2.
- 24. If spectrum analyzer is an 8561E, skip to step 27.
- 25. Press (1). Record the PRESEL SLOPE DAC value for Band 2 in Table 2-2.
- 26. Press (1). Record the PRESEL SLOPE DAC value for Band 3 in Table 2-2.

Table 2-2. Preselector DAC Values

Band Number	PRESEL OFFSET DAC	PRESEL SLOPE DAC
Band 1		
Band 2*		
Band 3*		
* Applies only	to 8563E.	

- 27. Place WR PROT/WR ENA jumper on the A2 controller assembly in the WR PROT position. Set the spectrum analyzer LINE switch off.
- 28. Follow the EEROM update procedure that is found in the instructions in the EEROM upgrade kit.

Install the New Firmware

This procedure is used if you only are replacing the firmware ROMs. Do not perform the procedure if you are replacing the entire A2 controller assembly.

- 1. Remove the spectrum analyzer cover assembly. This is described in procedure 1 of Chapter 3 in this note.
- 2. Fold down the A2 controller assembly.
- 3. Locate the six firmware ROMs, A2U306 through A2U311. The Agilent 8560 E-Series Spectrum Analyzer Component-Level Information includes component location drawings.
- 4. Carefully pry the ROMs upward using a small-blade screwdriver.

Caution

To prevent damage to the ROMs, make sure that the ROMs are oriented correctly in the sockets on the A2 assembly. Match the notch at the end of each ROM with the notch at the end of its socket. Align each ROM IC pin with the opening of its pin receptacle on the socket.

5. Install each ROM by carefully pushing down on both ends of the ROM with equal pressure.

Download the Serial Number and ID String (for original firmware <930809 only)

This procedure is only required for the 8560E, 8561E and 8563E. See "What You'll Find in This Installation Note" for information about the appropriate serial numbers.

- 1. Move the WR PROT/WR ENA jumper on the A2 controller assembly to the WR ENA position.
- 2. Set up the computer as described in the operation verification chapter of the calibration guide (or the installation and verification manual, shipped with earlier instruments). Connect an GPIB cable between the computer and the spectrum analyzer.
- 3. Connect a power cord to the spectrum analyzer and set the LINE switch ON. Wait for the power-on adjustments to complete. Ignore any error messages.
- 4. On the spectrum analyzer, press CONFIG, ANALYZER ADDRESS. If the current address is not 18, press 18, (ENTER) (the (Hz) key), and STORE GPIB ADR.
- 5. Load and run the FW_UPGRADE program on the A2 firmware upgrade software disc supplied with the kit. This program is used to download the spectrum analyzer serial number and ID string into its EEROM. This information must be present for the spectrum analyzer to function correctly.
 - a. The software will prompt you to enter the serial number prefix and the serial number suffix. For example, if the complete serial number is 3221 A00129, enter 3221 for the prefix (the program will automatically append the A) and enter 00129 for the suffix.
 - b. Next you will be prompted to enter the spectrum analyzer model number. A list of valid model numbers will be displayed. Enter the model number exactly as it appears in the list. All alphabetic characters must be upper-case.
 - c. You will then be prompted to indicate if there are any options installed. If the serial prefix is 3305A or below, answer 'Y' (yes) and enter Option 008; these analyzers have the signal identification feature as standard. If there are any other options installed, add the appropriate option number. Enter a Q (quit) if there are no more options to add to the ID string.
 - d. This program can be used a maximum of three times. If a successful download of the serial number and ID string cannot be obtained in three attempts, it will be necessary to send the spectrum analyzer to an Agilent customer service center to complete the installation.
- 6. After successfully downloading the new ID string, turn the spectrum analyzer power off and on. Some error messages will still appear; these will be cleared later.
- 7. Press CONFIG DATECODE &OPTIONS. Under Options: should appear the spectrum analyzer model number and 008 (if the serial prefix is 3305A or below) along with any other installed options.

Reload the EEROM Data (for original firmware <930809 only)

This procedure is only required for the 8560E, 8561E and 8563E. See "What You'll Find in This Installation Note" for information about the appropriate serial numbers.

- 1. Press (DISPLAY), INTENSTY, 120, (ENTER) (the (Hz) key), and STORE INTENSTY.
- 2. Press MORE 1 OF 2, FOCUS, 128, (ENTER), STORE FOCUS.
- 3. Press (SAVE), PWR ON STATE.
- 4. Connect a BNC cable from the CAL OUTPUT to INPUT 50 Ω .
- 5. Press (CAL), MORE 1 OF 2, SERVICE CAL DATA, 3RD IF AMP. Press CAL 3RD AMP GAIN and wait until the message ADJUSTMENT DONE is displayed.
- 6. If the spectrum analyzer is not an 8560E with Option 002, press EXT MXR REF CAL. Enter the value recorded in step 5 in the "Record the EEROM Data" procedure.
- 7. Press PREV MENU, STORE DATA, YES.
- 8. On the spectrum analyzer, press (PRESET), and set the controls as follows:

Center frequency	 1.45 GHz
Span	 0 Hz

- 9. Press (CAL), MORE 1 OF 2, SERVICE CAL DATA, LO LEVELS, LO GATE LEVEL. Enter the LO GATE DAC value from Table 2-1.
- 10. Press INT LO LEVEL. The message DRIVE FOR BAND# 0 should be displayed. Enter the LO DRIVE DAC value for Band 0 from Table 2-1.
- 11. If the spectrum analyzer is an 8560E skip to step 16.
- 12. Press (1). The message DRIVE FOR BAND# 1 should be displayed. Enter the LO DRIVE DAC value for Band 1 from Table 2-1.
- 13. If the spectrum analyzer is an 8561E skip to step 16.
- 14. Press (1). The message DRIVE FOR BAND# 2 should be displayed. Enter the LO DRIVE DAC value for Band 2 from Table 2-1.
- 15. Press 介. The message DRIVE FOR BAND# 3 should be displayed. Enter the LO DRIVE DAC value for Band 3 from Table 2-1.
- 16. Press EXT LO LEVEL. Enter the LO DRIVE DAC value for External mixing from Table 2-1.
- 17. If spectrum analyzer is an 8561E, press BAND 1 MXR BIAS. Enter the INT MXR BIAS DAC value recorded in step 15 of the "Record the EEROM Data" procedure.
- 18. Press PREV MENU, STORE DATA, YES.
- 19. If the spectrum analyzer is an 8560E, skip to step 29.
- 20. On the spectrum analyzer, press (PRESET), and set the controls as follows:

Center frequency	4.0	GHz
Span		0 Hz

- 21. Press (CAL), MORE 1 OF 2, SERVICE CAL DATA, PRESEL ADJ, PRESEL OFFSET. Enter the PRESEL OFFSET DAC value for Band 1 from Table 2-2.
- 22. If the spectrum analyzer is an 8561E, skip to step 25.

- 23. Press (1). Enter the PRESEL OFFSET DAC value for Band 2 from Table 2-2.
- 24. Press (1). Enter the PRESEL OFFSET DAC value for Band 3 from Table 2-2.
- 25. Press PRESEL SLOPE. If necessary, press (\mathbb{T}) until the message SLOPE FOR BAND # 1 is displayed. Enter the PRESEL SLOPE DAC value for Band 1 from Table 2-2.
- 26. If the spectrum analyzer is an 8561E, skip to step 29.
- 27. Press (1). Enter the PRESEL SLOPE DAC value for Band 2 from Table 2-2.
- 28. Press (1). Enter the PRESEL SLOPE DAC value for Band 3 from Table 2-2.
- 29. Press PREV MENU, STORE DATA, YES.
- 30. Turn the spectrum analyzer power off and on again. Wait for the power-on adjustments to complete. A few error messages will still appear; these will be cleared later.

Perform the Frequency Response Adjustment (for original firmware <930809 only)

This procedure is only required for the 8560E, 8561E and 8563E. See "What You'll Find in This Installation Note" for information about the appropriate serial numbers,

- 1. If an Agilent 85629B test and adjustment module (TAM) is available, perform the Low Band Flatness. If the spectrum analyzer is an 8561E or 8563E, perform the High Band Flatness and YTF adjustments in the TAM's adjust menu.
- 2. If a TAM is not available, perform the appropriate frequency response adjustment procedure in Chapter 3 of this note:
 - a. 8560E Procedure 3
 - b. 8561E Procedure 4
 - c. 8563E Procedure 5
- 3. If the spectrum analyzer is an 8561E or 8563E, press (SAVE), SAVE PRSEL PK.
- 4. Move the WR PROT/WR ENA jumper on A2 to the WR PROT position.

Reassemble the Spectrum Analyzer

This procedure is used for all 8560 E-Series spectrum analyzers.

- 1. Fold up the A2 and A3 board assemblies as described in procedure 2 in Chapter 3 in this note.
- 2. Install the spectrum analyzer cover as described in procedure 1 in Chapter 3 in this note.
- 3. The retrofit is complete. Running the operation verification software is recommended.

Replacement and Adjustment Procedures

Spectrum Analyzer Cover Procedure 1.

Removal/Replacement

- 1. Disconnect the line-power cord, remove any adapters from the front-panel connectors, and place the analyzer on its front panel.
- 2. If an 85620A mass memory module is mounted on the rear panel, remove it. Loosen (but do not remove) the four rear-bumper screws, using a 4 mm hex wrench. Pull the cover assembly off towards the rear of the instrument.

Caution When replacing the spectrum analyzer cover, use caution to avoid damaging any cables.

- 3. When installing the cover assembly, be sure to locate the cover's air vent holes on the bottom side of the spectrum analyzer. Attach with the four screws loosened in step 2, and tighten the four screws gradually to ensure that the cover is seated in the front-frame gasket groove.
- 4. Torque each screw to 40 to 50 inch-pounds to ensure proper EMI gasket compression.




Figure 3-1. Hinged Assemblies

Procedure 2. A2, A3, A4, and A5 Assemblies

Removal

- 1. Remove the spectrum analyzer cover,
- 2. Place the spectrum analyzer on its right side frame.
- 3. Remove the eight screws holding the A2, A3, A4, and A5 assemblies to the top of the analyzer. These screws are labeled (2), (3), and (4) in Figure 3-2. They are also labeled on the back of the A2 board assembly.
- 4. Remove ribbon cable W4 from A2J6. See Figure 3-2.

Caution

Do not fold the board assemblies out of the spectrum analyzer one at a time. Always fold the A2 and A3 assemblies as a unit and the A4 and A5 assemblies as a unit. Folding out one assembly at a time binds the hinges attaching the assemblies and may damage an assembly and hinge.

- 5. The board assemblies are attached to the spectrum analyzer right side frame with two hinges. Fold both the A2 and A3 assemblies out of the analyzer as a unit.
- 6. Fold both the A4 and A5 assemblies out of the spectrum analyzer as a unit.
- 7. Remove the cables from the assembly being removed, as illustrated in Figure 3-3.
- 8. Remove the two screws that attach the assembly being removed to its two mounting hinges.

Caution

Do not torque shield TORX screws to more than 5 inch-pounds. Applying excessive torque will cause the screws to stretch.




Figure 3-2. A2, A3, A4, and A5 Assembly Removal

Replacement

- 1. Place the spectrum analyzer top-side-up on the work bench.
- 2. Attach the assembly being installed to the two chassis hinges with two panhead screws.
- 3. Leave the assembly in the folded-out position and attach ribbon cables W1 and W2.
- 4. Attach all coaxial cables to the assembly, as illustrated in Figure 3-3.
- 5. Locate the cable clip on the inside of the right-side frame. Make sure that the coaxial cables are routed properly on the clip as illustrated in Figure 3-4.
- 6. Lay the A2, A3, A4, and A5 assemblies flat against each other in the folded-out position. Make sure that no cables become pinched between any two assemblies.




Figure 3-3. Assembly Cables (1 of 2)





Figure 3-3. Assembly Cables (2 of 2)

Installation Note 08560-90164

SK131



s I 19e

Figure 3-4. Coaxial Cable Clip

- 7. Check to ensure that no cables will become pinched under the hinges when folding up the A4 and A5 assemblies.
- 8. Fold the A4 and A5 assemblies together as a unit into the analyzer. Use caution to avoid damaging any cable assemblies. The standoffs on the A5 assembly must fit into the cups on the A6 power supply top shield.
- 9. Fold the A2 and A3 assemblies together as a unit into the spectrum analyzer. Be sure to fold GPIB cable A19W1 between the A3 and A4 assemblies, using the two sets of hook and loop (Velcro) fasteners.
- 10. Fold ribbon cable A1A1W1 between A3 and A4 assemblies. Take care to dress the protective tubing as close to A3J602 connector as possible, so that the tubing does not fold with the cable. See Figure 3-5.
- 11. Attach ribbon cable W4 to A2J6 while folding up the assemblies. See Figure 3-2.
- 12. Secure the assemblies using the eight screws removed in "Removal" step 3.




Figure 3-5. GPIB and A1A1 W1 Cable Placement

Procedure 3. 8560E Frequency Response Adjustment

Assembly Adjusted

A15 RF Assembly

Related Performance Tests

Displayed Average Noise Level Frequency Response

Description

A signal of the same known amplitude is applied to the spectrum analyzer at several different frequencies. At each frequency, the DAC controlling the flatness compensation amplifiers is adjusted to place the peak of the displayed signal at the same place on the screen. With firmware revisions greater than 920528, there are correction points at 2 MHz and 6 MHz. These points are outside the synthesized sweeper's frequency range. The DAC values for these two points are set to a fixed offset from the DAC value at 10 MHz. The DAC values are stored in EEROM.




Figure 3-6. Frequency Response Adjustment Setup

sj142e

Equipment

Synthesized sweeper	8340A/B
Measuring receiver	8902A
Power sensor	8482A
Power splitter	11667A
Adapters	
Type-N (m) to Type-N (m)	250-1475
Type-N (m) to APC 3.5 (f)	250-1744
Type APC 3.5 (f) to APC 3.5 (f)	061-5311
Cables	
BNC, 122-cm (48 in)	10503A
APC 3.5, 91-cm (36 in)	20-4921

Procedure

- 1. Connect the equipment as shown in Figure 3-6. Do not connect the 8482A power sensor to the Agilent 11667A power splitter.
- 2. Zero and calibrate the Agilent 8902A/8482A combination in log mode (power levels read out in dBm) and connect the power sensor through an adapter to the power splitter.
- 3. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR ENA position.
- 4. Press (PRESET) on the 8560E and set the controls as follows:

Center Frequency	MHz
Span	0 Hz
Resolution bandwidth	kHz
dB/division	2 dB

5. Press (INSTR PRESET) on the 8340A/B and set the controls as follows:

CW frequency	
Power level	

- 6. On the 8560E, press (MKR), (CAL), MORE 1 OF 2, SERVICE CAL DATA, then FLATNESS. The current value of the RF gain DAC should be displayed in the active function area. If the frequency displayed in the active function area is not 10 MHz, press (n) or (1) until 10 MHz is displayed.
- 7. Enter the appropriate power sensor calibration factor into the 8902A.
- 8. Set the Agilent 8340A/B (CW) output to the frequency indicated in the active function area of the 8560E display. Adjust the 8340A/B power level for a -10 dBm reading on the 8902A.
- 9. On the 8560E spectrum analyzer, adjust the RF gain DAC value using the front-panel knob or keypad until the marker reads $-10 \text{ dBm} \pm 0.10 \text{ dB}$. Each DAC count yields an approximate 0.01 dB change.
- 10. On the spectrum analyzer, press (1) to proceed to the next frequency.
- 11. Repeat steps 7 through 10 for all low-band frequencies ≥10 MHz.
- 12. If the firmware revision is later than 920528, perform steps 13 through 17. Otherwise, skip to step 18.

13.	Press (1) until 10 MHz is displayed in the active function block. Record the RF gain DAC value at 10 MHz.
	10 MHz RF gain DAC value
14.	Add 67 to the 10 MHz RF gain DAC value and record as the 2 MHz RF gain DAC value.
	2 MHz RF gain DAC value
15.	Add 62 to the 10 MHz RF gain DAC value and record as the 6 MHz RF gain DAC value.
	6 MHz RF gain DAC value

- 16. Press 🕕 until 2 MHz is displayed in the active function block. Use the DATA keys to enter the 2 MHz RF gain DAC value recorded in step 14.
- 17. Press (n) until 6 MHz is displayed in the active function block. Use the DATA keys to enter the 6 MHz RF gain DAC value recorded in step 15.
- 18. Press PREV MENU, STORE DATA, then YES on the 8560E.
- 19. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR PROT position.

Procedure 4. 8561E Frequency Response Adjustment

Assembly Adjusted

A15 RF Assembly

Related Performance Tests

Displayed Average Noise Level Frequency Response

Description

A signal of the same known amplitude is applied to the spectrum analyzer at several different frequencies. At each frequency, the DAC controlling the flatness compensation amplifiers is adjusted to place the peak of the displayed signal at the same place on the screen. The preselector is centered at each frequency before setting the other DAC value. With firmware revisions greater than 920528, there are correction points at 2 MHz and 6 MHz. These points are outside the synthesized sweeper's frequency range. The DAC values for these two points are set to a fixed offset from the DAC value at 10 MHz. The DAC values are stored in EEROM.




Figure 3-7. Frequency Response Adjustment Setup

SK112

Equipment

Synthesized sweeper8340A/BMeasuring receiver8902APower sensor8482APower sensor8485APower splitter11667B
AdaptersType-N (m) to Type-N (m)1250-1475Type-N (m) to APC 3.5 (m)1250-1743Type-N (f) to APC 3.5 (m)1250-1750Type APC 3.5 (f) to APC 3.5 (f)5061-5311
Cables BNC, 122-cm (48 in)

Procedure

Note

The YIG-tuned filter/mixer slope and offset adjustment must be correct before the high band part of the frequency response adjustment can be done.

- 1. Connect the equipment as shown in Figure 3-7. Do not connect the 8482A power sensor to the 11667B power splitter.
- 2. Zero and calibrate the 8902A/8482A combination in log mode (power levels read out in dBm) and connect the power sensor through an adapter to the power splitter.
- 3. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR ENA position. The jumper is on the edge of the A2 board assembly and can be moved without folding the board down.
- 4. Press (PRESET) on the 8561E and set the controls as follows:

Center frequency) MHz
Span	.0 Hz
Resolution bandwidth 30	0 kHz
dB/division	2 dB

5. Press (INSTR PRESET) on the 8340A/B and set the controls as follows:

CW		MHz
POWER LEVEL	-4 (dBm

- 6. On the 8561E, press (MKR) (CAL) MORE 1 OF 2 SERVICE CAL DATA, then FLATNESS. The current value of the RF Gain DAC should be displayed in the active function area.
- 7. Enter the appropriate power sensor calibration factor into the 8902A.
- 8. Set the 8340A/B (CW) output to the frequency indicated in the active function area of the 8561E display. Adjust the 8340A/B POWER LEVEL for a -10 dBm reading on the 8902A.
- 9. On the 8561E, adjust the RF Gain DAC value using the front-panel knob or keypad until the marker reads -10 dBm ± 0.10 dB. Each DAC count results in an amplitude change of approximately 0.01 dB.
- 10. On the 8561E, press (♠) to proceed to the next frequency.

- 11. Repeat steps 7 through 10 for all low-band frequencies >10 MHz.
- 12. If the firmware revision is later than 920528, perform steps 13 through 17. Otherwise, skip to step 18.
- 13. Press (1) until 10 MHz is displayed in the active function block. Record the RF gain DAC value at 10 MHz.

	10	MHz	RF	gain	DAC	value	
--	----	-----	----	------	-----	-------	--

14. Add 67 to the 10 MHz RF gain DAC value and record as the 2 MHz RF gain DAC value.

2	MHz	RF	gain	DAC	value	

15. Add 62 to the 10 MHz RF gain DAC value and record as the 6 MHz RF gain DAC value.

6	MHz	RF	gain	DAC	value	
---	-----	----	------	-----	-------	--

- 16. Press (1) until 2 MHz is displayed in the active function block. Use the DATA keys to enter the 2 MHz RF gain DAC value recorded in step 14.
- 17. Press (f) until 6 MHz is displayed in the active function block. Use the DATA keys to enter the 6 MHz RF gain DAC value recorded in step 15.
- 18. Press NEXT BAND on the 8561E.
- 19. Disconnect the 8482A and its adapter from the 11667B. Connect the 8485A to the 8902A. Zero and calibrate the 8902A/8485A combination. Connect the 8485A to the 11667B power splitter.
- 20. Enter the appropriate power sensor calibration factor into the 8902A.
- 21. Set the 8340A/B (cw) output to the frequency indicated in the active function area of the 8561E display.
- 22. Adjust the 8340A/B POWER LEVEL to place the signal midscreen on the 8561E display.
- 23. On the 8561E, press PRESEL AUTO CTR.
- 24. Adjust the 8340A/B POWER LEVEL for a -10 dBm reading on the 8902A.
- 25. On the 8561E, adjust the RF gain DAC value using the knob or keypad until the marker reads $-10 \text{ dBm } \pm 0.10 \text{ dB}$.
- 26. On the 8561E, press (1) to proceed to the next frequency.
- 27. Repeat steps 21 through 27 for the remaining frequencies in Band 1.
- 28. Press PREV MENU STORE DATA, then YES on the 8561E.
- 29. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR PROT position.

Procedure 5. 8563E Frequency Response Adjustment

Assembly Adjusted

A15 RF Assembly

Related Performance Tests

Displayed Average Noise Level Frequency Response

Description

A signal of the same known amplitude is applied to the spectrum analyzer at several different frequencies. At each frequency, the DAC controlling the flatness compensation amplifiers is adjusted to place the peak of the displayed signal at the same place on the screen. The preselector is centered at each frequency before setting the DAC value. With firmware revisions greater than 920528, there are correction points at 2 MHz and 6 MHz. These points are outside the synthesized sweeper's frequency range. The DAC values for these two points are set to a fixed offset from the DAC value at 10 MHz. The DAC values are stored in EEROM. The DAC values are stored in EEROM.




Figure 3-8. Frequency Response Adjustment Setup

SK112

Equipment

Synthesized sweeper8340 A/BMeasuring receiver8902 APower sensor8482 APower sensor8485 APower splitter11667 B
AdaptersType-N (m) to Type-N (m)1250-1475Type-N (m) to APC 3.5 (m)1250-1743Type-N (f) to APC 3.5 (m)1250-1750Type APC 3.5 (f) to APC 3.5 (f)5061-5311
Cables 10503A BNC, 122-cm (48 in) 10503A APC 3.5, 91-cm (36 in) 8120-4921

Procedure

Note

The YIG-tuned filter/mixer slope and offset adjustment must be correct before the high band part of the frequency response adjustment can be done.

- 1. Connect the equipment as shown in Figure 3-8. Do not connect the 8482A power sensor to the 11667B power splitter.
- 2. Zero and calibrate the 8902A/8482A combination in log mode (power levels read out in dBm) and connect the power sensor through an adapter to the power splitter.
- 3. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR ENA position. The jumper is on the edge of the A2 board assembly and can be moved without folding the board down.
- 4. Press (PRESET) on the 8563E and set the controls as follows:

Center frequency	MHz
Span	.0 Hz
Resolution BW 300) kHz
dB/division	2 dB

5. Press (INSTR PRESET) on the 8340A/B and set the controls as follows:

CW frequency	 2
Power level	 l

- 6. On the 8563E, press (MKR) (CAL) MORE 1 OF 2 SERVICE CAL DATA, then FLATNESS. The current value of the RF Gain DAC should be displayed in the active function area.
- 7. Enter the appropriate power sensor calibration factor into the 8902A.
- 8. Set the 8340A/B (CW) output to the frequency indicated in the active function area of the 8563E display. Adjust the 8340A/B POWER LEVEL for a -10 dBm reading on the 8902A.
- 9. On the 8563E, adjust the RF gain DAC value using the front-panel knob or keypad until the marker reads -10 dBm ±0.10 dB. Each DAC count results in an amplitude change of approximately 0.01 dB.
- 10. On the 8563E, press (n) to proceed to the next frequency.

- 11. Repeat steps 7 through 10 for all low-band frequencies >10 MHz.
- 12. If the firmware revision is later than 920528, perform steps 13 through 17. Otherwise, skip to step 18.
- 13. Press nutil 10 MHz is displayed in the active function block. Record the RF gain DAC value at 10 MHz.

10 MHz RF gain DAC	value
--------------------	-------

14. Add 67 to the 10 MHz RF gain DAC value and record as the 2 MHz RF gain DAC value.

2	MHz	RF	gain	DAC	value	
_	1411177	Tri	Sam	DHO	varue	

15. Add 62 to the 10 MHz RF gain DAC value and record as the 6 MHz RF gain DAC value.

6	MHz	RF	gain	DAC	value	

- 16. Press (until 2 MHz is displayed in the active function block. Use the DATA keys to enter the 2 MHz RF gain DAC value recorded in step 14.
- 17. Press nutil 6 MHz is displayed in the active function block. Use the DATA keys to enter the 6 MHz RF gain DAC value recorded in step 15.
- 18. Press NEXT BAND on the 8563E.
- 19. Disconnect the 8482A and its adapter from the 11667B. Connect the 8485A to the 8902A. Zero and calibrate the 8902A/8485A combination. Connect the 8485A to the 11667B power splitter.
- 20. Enter the appropriate power sensor calibration factor into the 8902A.
- 21. Set the 8340A/B (CW) output to the frequency indicated in the active function area of the 8563E display.
- 22. Adjust the 8340A/B POWER LEVEL to place the signal midscreen on the 8563E display.
- 23. On the 8563E, press PRESEL AUTO CTR.
- 24. Adjust the 8340A/B POWER LEVEL for a -10 dBm reading on the 8902A.
- 25. On the 8563E, adjust the RF gain DAC value using the knob or keypad until the marker reads $-10 \text{ dBm} \pm 0.10 \text{ dB}$.
- 26. On the 8563E, press (1) to proceed to the next frequency.
- 27. Repeat steps 21 through 27 for the remaining frequencies in band 1.
- 28. On the 8563E, press NEXT BAND to proceed to band 2.
- 29. Repeat steps 21 through 27 for the remaining frequencies in band 2.
- 30. On the 8563E, press NEXT BAND to proceed to band 3.
- 31. Repeat steps 21 through 27 for the remaining frequencies in band 3.
- 32. Press PREV MENU STORE DATA, then YES on the 8563E.
- 33. Place the WR PROT/WR ENA jumper on the A2 controller assembly in the WR PROT position.