8564E-11

HP 8564E	Portable Spectrum Ana	SUPERSEDES: NONE	
Serial Numbers: 3635A00584 / 3711A00809			
Intermittent Error 337 (Frac-N Unlock) Under Certain Conditions			
Duplicate Ser	vice Notes:		
8560E-16, 8561E-13, 8562E-04, 8563E-16, 8565E-11			
To Be Performed By: HP-Qualified Personnel			
Parts Required:			
HP P/N	Description	Quanty	
08560-60086	Firmware Upgrade Kit	1 ea.	
Situation:			
the Fractional- condition sets	N phase lock loop is quickly tun	appear under certain tuning conditions where ed across its entire range during retrace. This willy cause the loop voltage to swing beyond	
Solution / Act	ion:		
Install firmware revision 970326 or later. If the part number listed above is not current, it has been superseded by a later part number.			
		DATE: July 1997	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours	
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: July 1999	
AUTHOR: GPB	ENTITY: 5320	ADDITIONAL INFORMATION:	

© 1997 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.

