

M62A

Supersedes: M62

This Service Note applies to support software provided with the following products.

11760, 8560, 8561, 8562, 8563, 8564, 8565, 8590, 8591, 8592, 8593, 8694, 8595, 8596, 83620, 83630, 83640, 83650, 83621, 83631, 83651, 83622, 83623, 83624, 83642, 8340, 8341, 8711, 8712, 8713, 8714, 8715, 8720, 8721, 8722, 8752, 8753, 83751, 83752, 83711, 83712, 83731, 83732  
Spectrum Analyzers, Sources and Network Analyzers.

Serial Numbers:

0000A00000 / 9999Z99999

Y2K update information. Microsoft Windows, Win 3.1, Win95 and Win98 software update information.

To Be Performed By: HP-Qualified Personnel, or Customer

Situation:

Support software running under the following operating systems; Microsoft Windows, Win 3.1, Win95 and Win98; and provided with products in the following families; 856X, 859X, 8360, 8340, 871X, 872X, 875X, 8375X, 8371X and 8373X; may need patches.

Solution / Action:

For the following platforms:

Microsoft Windows (Win 3.1, Win95 and Win98) contact Microsoft at URL: [www.microsoft.com](http://www.microsoft.com) for update information and patches.

Date:

December 1998

```
*****  
*                                                                 *  
*                               INFORMATION ONLY                       *  
*                               -----                               *  
*   AUTHOR/ENTITY: HU/5320                                           *  
*   ADDITIONAL INFO: _____                                       *  
*                                                                 *  
*****
```

Copyright Hewlett-Packard Company 1998