

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E4446A-07

S E R V I C E N O T E

Supersedes:
NONE

E4446A and E4448A

Serial Numbers: [0000A00000 / 9999Z99999]

Instruments with Firmware version A.05.06 may fail frequency response above 26.4 GHz or above. This issue is only observed with PSA Firmware version A.05.06.

Please upgrade the instrument to PSA firmware version A.05.07 or later. The firmware can be downloaded from the following URL:

www.agilent.com/find/psa_firmware

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
-----	-------------	------

None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.5 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: BNN	PRODUCT LINE: 12	AGILENT RESPONSIBLE UNTIL: Support Life	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



March 29, 2004

Situation:

Instruments with Firmware version A.05.06 may fail frequency response above 26.4 GHz or above. This issue is only observed with PSA Firmware version A.05.06.

Solution/Action:

Please upgrade the instrument to PSA firmware version A.05.07 or later. The firmware can be downloaded from the following URL:

www.agilent.com/find/psa_firmware