

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**E4448A-08**

**S E R V I C E N O T E**

Supersedes:  
NONE

E4446A and E4448A

Serial Numbers: [0000A00000 / 9999Z99999]

**Instruments with Firmware version A.05.06 may fail frequency response above 26.4 GHz or above. This issue is only observed with PSA Firmware version A.05.06.**

**Please upgrade the instrument to PSA firmware version A.05.07 or later. The firmware can be downloaded from the following URL:**

[www.agilent.com/find/psa\\_firmware](http://www.agilent.com/find/psa_firmware)

**To Be Performed By: Agilent-Qualified Personnel or Customer**

**Parts Required:**

P/N	Description	Qty.
-----	-------------	------

None

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	X IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.5 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: BNN	PRODUCT LINE: 12	AGILENT RESPONSIBLE UNTIL: Support Life	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2004  
PRINTED IN U.S.A.



March 29, 2004

**Situation:**

Instruments with Firmware version A.05.06 may fail frequency response above 26.4 GHz or above. This issue is only observed with PSA Firmware version A.05.06.

**Solution/Action:**

Please upgrade the instrument to PSA firmware version A.05.07 or later. The firmware can be downloaded from the following URL:

[www.agilent.com/find/psa\\_firmware](http://www.agilent.com/find/psa_firmware)