

## S E R V I C E N O T E

SUPERSEDES: None

**11807C Radio Test Software****Serial Numbers:** Installation Card revision A.02.xx and below**Duplicate Service Notes:** 8920DTS-02**New installation card revision A.03.00 corrects wrong connectivity test results due to system calibration effects.****To Be Performed By:** Agilent-Qualified Personnel or Customer Installable**Parts Required:**

Part No.	Qty.	Description
83215-85305	1	Installation Card (Epson Type) for 8920A
83215-85312	1	Installation Card (PCMCIA Type) for 8920B

**Situation:**

When a status of the system calibration for the 83215A or 83215B is ON, it affects connectivity test results. It makes most of the test results failure.

**Solution/Action:**

New revision of connectivity test (A.03.00) corrects the bug. Replace the customer's installation card with the new one.

DATE: July 1995

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.0 hrs		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: July 1997			
AUTHOR: YO	ENTITY: 3355	ADDITIONAL INFORMATION: FQC-139508			