

S E R V I C E N O T E

SUPERSEDES: NONE

37722/32A Telecom Analyzer Options B01/B48

Serial Numbers: 0000U00000/9999U99999

Impulse noise on external DC Supply may cause the unit to shutdown

Duplicate Service Notes: 37722A-04
37732A-09

Situation:

Impulse noise on external DC Supply may cause the unit to shutdown.

Solution / Action:

This can be rectified by adding 2 0.47mf capacitors to an earth lug.

Parts Required

P/N	Description	Quantity
0160-7716	CF MP 0.47mf 250V	2
0360-0040	TRM-SLDR LG 1/4L	1

DATE: May 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR .0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: GS	ENTITY: E610	AGILENT RESPONSIBLE UNTIL:	2001
		ADDITIONAL INFORMATION:	