

S E R V I C E N O T E

SUPERSEDES: 8920DTS-02

8920DTS Digital RF Communications Test System

Serial Numbers:

Installation Card revision A.03.00 and below (Epson type for 8920A)
Installation Card revision A.02.00 and below (PC Card type for 8920B)

New installation card corrects SYS_CONN program bug.

To Be Performed By: Agilent-Qualified Personnel or Customer installable

Parts Required:

Part No.	Qty.	Description
83215-85308	1	Installation Card (Epson type) for 8920A
or		
83215-85315	1	Installation Card (PC Card type) for 8920B

Continued

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.0 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: YO	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: January 1997	
		ADDITIONAL INFORMATION: FQC-139508 - 139523	



Situation 1:

When a status of the system calibration for the 83215A or 83215B is ON, it affects SYS_CONN test results. It makes most of the test results failure.

Situation 2:

Due to the 83215A power detector design change, T09 and T22 in the SYS_CONN program may be failed.

Solution/Action:

The new revision of installation card corrects the SYS_CONN bugs. Replace the customer's installation card with the new one.