

S E R V I C E N O T E

SUPERSEDES: None

8920DTS Digital RF Communications Test System

Serial Numbers: Installation Card revision A.02.xx and below

New installation card revision A.03.00 corrects wrong system calibration of 1428 MHz loss.

To Be Performed By: Agilent-Qualified Personnel or Customer Installable

Duplicate Service Notes: 11807C-02, 8920DTS-03

Parts Required:

Part No.	Qty.	Description
83215-85305	1	Installation Card (Epson Type) for 8920A
83215-85312	1	Installation Card (PCMCIA Type) for 8920B

Situation:

When performing system calibration, a loss value at 1428 MHz is slightly (about 1 dB) deviated from the correct value.

Solution/Action:

New revision of connectivity test (A.03.00) corrects the bug. Replace the customer's installation card with the new one.

DATE: July 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.0 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: YO	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: July 1997	
		ADDITIONAL INFORMATION: FQC-139508	