

S E R V I C E N O T E

SUPERSEDES: None

8920DTS Digital RF Communications Test System

Serial Numbers:

Installation Card revision A.03.00 and below (Epson type for 8920A)
 Installation Card revision A.02.00 and below (PC Card type for 8920B)

New installation card corrects system calibration for 83215B

To Be Performed By: Agilent-Qualified Personnel or Customers

Parts Required:

Part No.	Qty.	Description
83215-85308	1	Installation Card for 8920A, Rev.A.03.10
or		
83215-85315	1	Installation Card for 8920B, Rev.A.02.10

Situation:

About 0.8 dB or RF level output error remains after performing SYS_CALB due to program bug.

Solution/Action:

The new revision of installation card corrects the SYS_CALB bug.

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.0 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: YO	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: January 1997	
		ADDITIONAL INFORMATION: FQC-139518	