8922A-02B

Supercedes 8922A-02A

HP8922A GSM RF Test Set

Serial Numbers:
0000A00000 / 9999Z99999

Y2K update information.

Product requires hardware and firmware upgrade to 8922M to be Y2K compliant. Firmware below B.07.07 is not Y2K compliant to HP Standards.

To Be Performed By: HP-Qualified Personnel.

Parts Required:

HP P/N Description Quantity 8922A #G07 QMD Specials option 1 QMD Specials options do not appear on CPL - see http://hpweb.sqf.hp.com/qmdman/specials/options/index.htm for details and contacts

Situation:

Y2K investigation has identified that the response from the BASIC function TIMEDATE is defective. This defect exists now and a TIMEDATE call would fail now if called in any BASIC application. Detection of this bug has caused all 8922 instruments below firmware B.07.07 to be classified as Y2K non-compliant. This bug has not been reported by customers which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922A to return an incorrect date/time stamp on 1st January 2000.

Solution / Action:

An instrument upgrade (8922A #G07) needs to be performed to install hardware and firmware B.07.07 or above to meet HP Y2K compliance standards. This firmware fixes the TIMEDATE bug but does not affect any other date-related processes within the instrument.

The 8922A will return the correct date/time stamp on 1st January 2000, without modification. It is recommended that no upgrade is required.

Date: November 1998

* *	******	****************	* *
*			*
*	Mo	ODIFICATION AVAILABLE	*
*			*
*			*
*	REASON:	PERFORMANCE ENHANCEMENT _X	*
*	-or-	SERVICE/RELIABILITY ENHANCEMENT	*
*	ACTION CATEGORY:	AGREEABLE TIME	*
*	LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE	*
*		HP LOCATION X	*
*	AVAILABLE UNTIL:	END OF SERVICE LIFE	*
*	AUTHOR/ENTITY:	AS/E600	*
*	ADDITIONAL INFO:	QMD Specials options not on CPL- see above	*
*			*
* *	*****	* * * * * * * * * * * * * * * * * * * *	* *

Copyright Hewlett-Packard Company 1998