S E R V I C E N O T E

SUPERSEDES: None

8922B GSM BS Test Set

Serial Numbers: 3050A00101 / 3240A00160

Recommended Removal of Hardware

Duplicate Service Notes:

8922A-01 8922B-01 8922E-01 8922G-01

Parts Required: None

Situation:

Instruments with serial numbers noted above may have internal hardware (screw and nut) which is improperly attached to the A36 FIFO GPIO and A37 Sequence Controller assemblies. Refer to Figure 1 for location of these assemblies. The hardware can become separated from the assembly, contact other circuitry and may cause electrical damage.

Solution/Action:

Remove and discard the hardware. Specific locations are indicated in Figure 2. Check for and remove any loose hardware within the instrument. Re-calibration is not required.

Continued

DATE: 02 June 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY☐ ON SPECIFIED FAILURE☐ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE■ ON-SITE■ SERVICE CENTER	SERVICE ☐ RETURN USED ☐ RETURN INVENTORY: ☐ SCRAP ☐ SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: 01 June 1999
AUTHOR: LHL	ENTITY: 1000	ADDITIONAL INFORMATION:

© 1994 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 8922B-01




FIGURE 1
Top Internal View of HP 8922A/B/E/G

Service Note 8922B-01 Page 3




FIGURE 2
Location of Excess Screw and Nut Hardware