

## S E R V I C E N O T E

SUPERSEDES: NONE

**8922M GSM Test Set**

Serial Numbers: See below

**Potential power supply failure under normal use.****Duplicate Service Notes:**

8922M-01 3807U02089 / 3818U02309

8922S-01 3748U00805 / 3818U00836

**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

08922-60141 Bd Ay-Power Sply Continued

**Situation:**

QMD have identified a potential failure with the power supply assembly (08922-60141) under normal use. The symptoms of the failure are the unit dead or blowing fuses.

**Solution / Action:**

The power supply assembly (08922-60141) needs to be replaced following normal procedures provided in the ALR. QMD also has a stock of replacement 8922M's to provide where the customer impact is high.

DATE: August 1998

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: RS	ENTITY: E600	AGILENT RESPONSIBLE UNTIL: May 2000	
		ADDITIONAL INFORMATION: None	