

S E R V I C E N O T E

SUPERSEDES: None

**8922M GSM MS Test Set
A33 HOP Controller Board 08922-60202**

Serial Numbers: 0000A00000 / 9999Z99999

8922 Hop controller board U62 - component part number transition

Duplicate Service Notes:

8922M-05
8922X-02

To Be Performed By: Agilent-Qualified Personnel.

Situation:

8922P options H09/K09 and H17/K17 require an updated component U62 fitted on the A33 Hop Controller board 08922-60202. The new ROM is 08922-87390. Options H09/K09/H17/K17 are currently being trialled with selected customers prior to release and may be installed on some units returned for repair.

Solution / Action:

If it is necessary to replace the Hop controller board during a repair, check which U62 ROM is fitted. If 08922-87390 is in the faulty board it should be installed in the new board during the repair and the ROM that comes with the new board (08922-87057) discarded.

DATE: December 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AS	E600	None