

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

J2126A-06

S E R V I C E N O T E

Supersedes:
NONE

AGILENT J2126A Transmission Test Set

Serial Numbers: [0000A00000 / 9999Z99999]

Motherboard pins can easily be bent if proper care is not exercised while inserting PC boards. Correct alignment between pins and connector must be obtained before final engagement between connectors.

Parts Required:

P/N	Description	Qty.
------------	--------------------	-------------

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: [initials]	PRODUCT LINE: [product line]
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2001
PRINTED IN U.S.A.



January 15, 2002

Situation:

Motherboard pins can be easily bent if the motherboard connector pins and PC board sockets are not aligned before the connection is pushed home

Solution/Action:

When inserting PC boards, observe the following precautions.

- 1. Perform a visual check on the motherboard connector pins for any damage.**
- 2. Check the locating lugs on the PC board connector for any damage (located at the centre of the board connector)**
- 3. Ensure the PC board is perfectly horizontal when being inserted into the board guides.**
- 4. Ensure proper registration between pins and sockets before final insertion.**