

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**J2127A-06**

**S E R V I C E N O T E**

---

Supersedes:  
NONE

**AGILENT J2127A Transmission Test Set**

**Serial Numbers:** [0000A00000 / 9999Z99999]

**Motherboard pins can easily be bent if proper care is not exercised while inserting PC boards. Correct alignment between pins and connector must be obtained before final engagement between connectors.**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
------------	--------------------	-------------

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
AUTHOR: [initials]	PRODUCT LINE: [product line]
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2001  
PRINTED IN U.S.A.



January 15, 2002

**Situation:**

Motherboard pins can be easily bent if the motherboard connector pins and PC board sockets are not aligned before the connection is pushed home

**Solution/Action:**

**When inserting PC boards, observe the following precautions.**

- 1. Perform a visual check on the motherboard connector pins for any damage.**
- 2. Check the locating lugs on the PC board connector for any damage ( located at the centre of the board connector)**
- 3. Ensure the PC board is perfectly horizontal when being inserted into the board guides.**
- 4. Ensure proper registration between pins and sockets before final insertion.**