

S E R V I C E N O T E

SUPERSEDES: None

3070 Board Test System

Serial Numbers: 0000A00000 / 9999Z99999

DGN Test 2124 fails at revision B.03.20 and higher**Situation:**

DGN test 2124 "Check MOA noise" failures have been experienced at software revision B.03.20 and higher. Investigation of test 2124 has revealed 3 defects in the 3070 diagnostics software for this test. Timing enhancements at B.03.20 revision of software have been identified as the cause of the defects in test 2124 surfacing. If you are at revision B.03.20 or higher, failures that you experience with test 2124 will not compromise the quality of the products that you test on your 3070 Boardtest system(s). There is no affect to normal testplan or test execution. MTD's recommendation is to continue testing your product as you normally would.

NOTE:

The above recommendation is valid only for failures of test 2124. MTD has not found other diagnostic tests failing as a result of test 2124 failing. Should other diagnostic tests fail, please use the existing process that you have in place to handle DGN failures.

Solution / Action:

The 3 defects that were found will be addressed using HP's normal defect process. For CE questions or concerns, please contact your local MSKC representative. For customer questions or concerns, please contact your local Board Test Representative.

DATE: November 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

