

M78B

Supersedes M78A

HP 3070 Series II Board Test Systems:

E3774A, E3775A, E3776A, E3778A, E3779A/B, E4011A, E4012A, E4015A,  
E4016A/B, E4017A/B, E4018A/B, E4019A, E4020A, E4021A, E4022A,  
E4023A, E4024A

HP 3070 Series II Controllers:

E3782A/AR, E3782B, E4005A/AR, E4005B/BR, E4005C/CR, E4007A, E4027A,  
E4027B, E4029A

Y2K update information:

To become Year 2000 Compliant Series II Systems, including Telecom Systems  
require revision B.03.xx software. Software revisions A.01.xx through  
A.02.xx are not Year 2000 compliant.

To Be Performed By: HP-Qualified Personnel

Situation:

HP 3070 Series II Systems have been discontinued. These systems can  
be made compliant by installing software revision B.03.xx. Customers  
who do not update to revision B.03.xx software will see some  
inconsistencies between utilities in the operating system and reports  
will have the date formatted incorrectly.

Solution / Action:

Shipments after 1/1/97 to Present

Revision B.03.xx software will be shipped to customers with an HP Support  
Agreement. Non-contract customers can order product E9930A, Option 600.

Serial Numbers 1/1/97 to present:

US34230309, US34230449 / US34230450, US34230453 / US34230454, US34230466,  
US34230469, US34230475 / US34230476, US34230479 / US34230555, US34230557,  
US34230558 / US34230678, US34230680 / US34230687, US34230689, US34230691,  
US34230692 / US34230693, US34230695 / US34230738, US34230740 / US34230755,  
US34240037, US34240119, US34240220, US34240243, US34240260, US34240262,  
US34240299, US34240302, US34240326, US34240341, US34240343, US34240359,  
US34240384, US34240400, US34240415, US34240428, US34240475, US34240508,  
US34240511, US34240513 / US34240525, US34240527 / US34240767, US37280102,  
US37280117, US37280121, US37280122, US37280156, US37280165, US37280175  
US37280176, US37280177, US37280179, US37280185 / US37280195, US37280197,  
US37280198 / US37280245, US37280247 / US37280248 / US37280253, US37280255,  
US37280256, US37280258 / US37280268, US37280271 / US37280288

Shipments from 1/1/95 to 12/31/96

B.03.xx revision software will be shipped to customers with an HP Support  
Agreement. Non-contract customers must purchase product E9930A.

Serial Numbers 1/1/95 to 12/31/96

US34230011, US34230040, US34230046, US34230056, US34230072, US34230074,  
US34230075, US34230077, US34230083, US34230085, US34230087, US34230090,  
US34230094, US34230096, US34230101 / US34230104, US34230106, US34230108,  
US34230109 / US34230199, US34230201 / US34230244, US34230246, US34230247,  
US34230248 / US34230300 / US34230308, US34230310 / US34230452,  
US34230455 / US34230465, US34230467, US34230468, US34230470 / US34230474,  
US34230477, US34230478, US34230481, US34240015, US34240026, US34240030,  
US34240043, US34240045, US34240051, US34240077, US34240078,  
US34240088, US34240089, US34240091, US34240092, US34240094 / US34240097,  
US34240102 / US34240105, US34240109 / US34240114, US34240116, US34240117,  
US34240118, US34240120 / US34240145, US34240147 / US34240149, US34240151,  
US34240152 / US34240154, US34240156 / US34240219, US34240221,  
US34240222 / US34240242, US34240244 / US34240251, US34240253,  
US34240254 / US34240259, US34240261, US34240263 / US34240301,  
US34240303 / US34240325, US34240327 / US34240340, US34240342,  
US34240344 / US34240383, US34240385 / US34240399, US34240401,  
US34240402 / US34240414, US34240416 / US34240436, US34240453,

