

## S E R V I C E N O T E

SUPERSEDES: 5DX-96-01  
Dated March 21, 1996

## HP 5DX Structural Process Test Systems

### Motion Control (Z-Axis)

**Situation:**

Possible Z-Axis stepper motor failure due to metal grit on the ball screw assembly.

**Solution:**

Be aware that early Z-Axis stepper motor failure is a high probability. Replace defective Z-Axis stepper motors (E7200-63605).

DATE: September 1997

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## INFORMATION ONLY

AUTHOR:

SM

ENTITY:

0982

ADDITIONAL INFORMATION: