# S E R V I C E N O T E

SUPERSEDES: None

## **5DX- Series II Test System**

### **Possible PDU Damage**

#### **Situation:**

During the installation of a HP 5DX Series 2L the Power Distribution Unit was damaged due to a pinched primary power input wire. This caused one of the circuit breakers to be damaged resulting in replacement of the PDU.

#### **Solution:**

Work with the customer's electrician to double check that none of the interconnect wiring is caught between the PDU chassis and the safety cover when the safety cover is installed after the primary power connections are made.

DATE: June 2001

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICAT	TION:	
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
KDP	0980	

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

