S E R V I C E N O T E

SUPERSEDES: NONE

E8400A C-Size VXI Mainframe, 13-Slot

Serial Numbers: 0000A00000 / 9999Z99999

Two resistors in the fan switching circuit are being operatated beyond their power rating.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Quantity

E8400-66599 PCA POWER SUPPLY INTERFACE 1

Situation:

When the fan is in the full speed mode resistors R114 and R116 are being operated at greater than 140% of their power rating.

Solution / Action:

Replace the E8400-66599 Power Supply Interface Assembly with one which has been modified.

DATE: September 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 2000
AUTHOR: DMT	ENTITY: 0960	ADDITIONAL INFORMATION:

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

