

S E R V I C E N O T E

SUPERSEDES: NONE

E8402A VXI Mainframe, C-Size, 13-Slot, 500 Watt

Serial Numbers: US38000000 / US38000775

Recommend Replacement Capacitor in Fan Power Supply

Duplicate Service Notes: E8401A-01

To Be Performed By: Agilent-Qualified Personnel / Customer

Parts Required:

P/N	Description	Quantity
E8401-69276	RBLT 0950-3276 600W PWR SUPPLY	1

Situation:

A capacitor in the fan supply of the E8401A power supply is failing.

Solution / Action:

Replace the power supply (0950-3276) with a modified exchange power supply assembly (p/n E8401-69276). Refer to "Replacing the 8401A Power Supply" in the E8401A/E8403A User/Service manual for power supply replacement instructions.

Note:

Modified exchange assemblies will have a serial number of KR935XXXXX or greater.

DATE: September 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: DMT	ENTITY: 0960	AGILENT RESPONSIBLE UNTIL: September 2001	
		ADDITIONAL INFORMATION:	

