

S E R V I C E N O T E

SUPERSEDES: NONE

E8491B IEEE-1394 PC Link to VXI, C-Size

Serial Numbers:

US39000000 - US39000125, US39000127 - US39000142,
 US39000144 - US39000153, US39000155 - US39000165,
 US39000167 - US39000181, US39000183 - US39000197,
 US39000199 - US39000201, US39000206, US39000208, US39000220

The E8491B front panel is incorrectly labeled.

To Be Performed By: Agilent-Qualified Personnel / Customer

Parts Required:

P/N	Description	Quantity
E8491-84303	Label, Front Panel Connect	1

Situation:

The front panel (E8491-00202) silkscreen for the E8491B is incorrect.

It is currently labeled:

- Trig Out
- Trig In
- Clk Out
- Clk In

Continued

DATE: September 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.1 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
		USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: September 2000
AUTHOR: DMT	ENTITY: 0960	ADDITIONAL INFORMATION:	



The front panel should be labeled as follows:

Clk In

Clk Out

Trig In

Trig Out

Solution / Action:

Use label (E8491-84303) to cover incorrect front panel input/output markings.